Notice of Potential National Pollution Discharge Elimination System (NPDES) PERMIT VIOLATIONS

Permittee (facility) Name and Address:
RUCKAWA-1 BEACH WASTE WATER TREATMENT FACILITY
1000 13045 CAMPROAD.
ROCKAWAY BEACH, MO65740
NPDES Permit Number: M0-0108162
During the Clean Water Act § 308 compliance inspection conducted on SEPTEMBER 11, 2007 the potential NPDES permit violations noted below were found. Additional violations may be brought to your attention following a complete review of the inspection report and other available information.
POTENTIAL NPDES PERMIT VIOLATIONS
FAILED TO MAKE A SUBMITTAL OF THE YEAR ZOOL SLUDGE IZEPORT AS REQUIRED BY STANDARD CONDITION, PARTILL, SECTION K(ZXQ). THE REPORT WAS DUE JANUARY 23, 2007.
DETERMINATION OF BIOCHEMICAL OXYGEN DEMAND (BOD), TOTAL SUSPENDED SOLIDS (TSS), POTENTIAL HYDROGEN ION (PH), FECAL COLIFORM (FC), TOTAL PHOSPHORUS AS P (TP) AMMONIA AS N(NH3-N AND OILAND GREITS E (ORG) WERE NOT BEING PERFORMED BY THE PLANT OPERATOR ASOR BY A CONTRACT LABURATORY.
REQUESTED ACTION: Within ten (10) days, please describe in writing any actions taken, or planned, to correct the potential violations identified above. Your response will be considered in the determination of the need for further administrative or legal action. Mail your description of corrective actions to your inspector at:
U.S. Environmental Protection Agency ENSV/EMWC
901 North 5 th Street
Inspector's printed name: Total Control of the Cont
JOSEPHAZ. YOSCIN JIZ.
Inspector's signature:
Notice received by: LARRY CLINE, MAYOR Jame & title)
Date: SEPT 13, 2007
INSPECTOR PAGE HI AE HI

Notice of Potential National Pollution Discharge Elimination System (NPDES)

PERMIT VIOLATIONS
Permittee (facility) Name and Address:
ROCKAWAY BEACH WASTE WATER TREATMENT FACILITY
1000 BOYS CAMP ROAD
120CKA WAY BEACH, MO 65740
NPDES Permit Number:
M0-0108162
During the Clean Water Act § 308 compliance inspection conducted on SEPTEMBER 1, 7007 the potential NPDES permit violations noted below were found. Additional violations may be brought to
your attention following a complete review of the inspection report and other available information.
POTENTIAL NPDES PERMIT VIOLATIONS
THE TEST PROCEDURE EQUIPMENT AND METHOD AVAILABLE TO DETERMINE AMMONIA AS N AND TOTAL PHOSPHORUS AS P FAIL TO WEET THE REQUIREMENTS GIVEN IN MOCERISG. BOTH TEST PROCEDURES REQUIRE DIGESTION AS AN INITIAL STEP WHICH IS NOT DONE
PROCESS CONTROL TESTS GIVEN AS REQUIRED AS STATED IN 10 CSR 20, CHAPTER 9 ARE INCORPORATED INTO THE NPDES FERNIT BY REFERENCE, THESE TESTS ARE NOT PERFORMED AT THE SPECIFIED FREQUENCY.
SPECIAL CONDITIONS IN THE NPDES PERMIT, PART C(2), ILEQUIRES THAT THE OUTFALL BE CLEARLY MARICED IN THE FIRITO, THE PRESENT MARKING DOES NOT IDENTIFY CLEARLY THAT AN OUTFALL EXISTS AND THE NATURE OF THE OUTFALL,
SPECIAL CONDITION IN THE NADIES PERMIT, PART C(8), REQUIRES SEMI-ANNAL REPORTS BE SUBMITTED WITH THE APRIL & OCTOBER DIME WHICH ADDRESS MEASURES TAKEN TO LOCATE AND ELIMINATE SOURCES OF INFLOW AND INFILTRATION INTO THE CITY'S COLLECTION SYSTEM, THESE REPORTS ARE NOT BEING PROVIDED TOMISSOURI DEPT OF NATURAL RESOURCES
REQUESTED ACTION: Within ten (10) days, please describe in writing any actions taken, or planned, to
correct the potential violations identified above. Your response will be considered in the determination of the need for further administrative or legal action. Mail your description of corrective actions to your
inspector at:
U.S. Environmental Protection Agency
ENSV/EMWC
901 North 5 th Street Kansas City, Kansas 66101-2907
Inspector's printed name: JOSEPH E. JOSLIN TR
Inspector's signature:
mispector's signature:
Notice received by: LARRICLINE, MAYOR LENE (name & title)
Date: SSM 13 71907
INSPECTOR PAGE 3 OF 4
110000

National Pollution Discharge Elimination System (NPDES) PERMIT VIOLATIONS

Permittee (facility) Name and Address:

TECHNICATE IS THEN WASTE WHITE THE THEORY
ROCKAWAY BEACH WASTEWATER TREATMENT FACILITY 1000 BOYS CAMP ROAD
ROCKAWAY BEACH, MO 65740
NPDES Permit Number: MO-0108162
During the Clean Water Act § 308 compliance inspection conducted on SEPTEMBER 11, 7007 the potential NPDES permit violations noted below were found. Additional violations may be brought to your attention following a complete review of the inspection report and other available information.
POTENTIAL NPDES PERMIT VIOLATIONS
FAILED TO MAINTAIN AND CALIBRATE THE FLOW MEASURING EQUIPMENT THE EFFLUENT FLOW METER READS A CONSTANT FLOW AND HEAD REGARDLE OF THE ACTUAL FLOW. THE ROCKAWAY BEACH INFLUENT FLOW METER READS A NEGATIVE HEAD AT ZERO FLOW. THE MERRIAM LUXISH BULL CREEK VILLAGE HEAD SENSOR IS IMPROPERLY LOCATED FOR THE PARSHALL FLUME BEING USED,
FAILED TO NAINTAIN THE EAST A ERATION TANK/CLARIFIER IN AN OPERAL STAND BY CONDITION, THIS SYSTEM HAS NOT BEEN RUN IN MORE THAN THYLEE YEARS. PRESENT STATUS OF AVAILABILITY IS UNKNOWN,
· FAILED TOMAINTAIN THE RECORDS REQUIRED BY STANDARD CONDITIONS PARTI, SECTION A(5), NONE OF THE RECORDS REQUIRED BY THIS SECTION WERE BEING KEPT.
THE NPDES PERMIT REQUIRES COMPOSITE SAMPLES FOR BOD, TSS AND THE WET TEST. WHEN THESE SAMPLES ARE COLLECTED, ONE A GRAB SAMPLIE IS COLLECTED,
REQUESTED ACTION: Within ten (10) days, please describe in writing any actions taken, or planned, to correct the potential violations identified above. Your response will be considered in the determination of the need for further administrative or legal action. Mail your description of corrective actions to your inspector at:
U.S. Environmental Protection Agency ENSV/EMWC
901 North 5 th Street Kansas City, Kansas 66101-2907
Inspector's printed name: Joseph E. Joseph J.
Inspector's signature:
Notice received by: LADOY CLINE MAYOR 19 19
Date: Sar 13 2007
INSPECTOR PAGE 2 OF 4